

















INDRA COMMODE




camif.fr




A	x38	B	x38	C	x26	D	x8	E	x54
		 Ø15		 8 x 30		 4 x 30		 4 x 40	

F	x12	G	x24	H	x24	I	x12	J	x28	K	x6
				 Ø 12		 8 x 50					
M4 x 16											







4)




5)




6)




7)




8)




9)




10)






11)





12)










16)

J	x16
	




17a)




G	x24	F	x12	K	x6
		 M4 x 16			
				E	x24
				 4 x 40	

17b) x6



17c)


x6





H	x24	J	x12

17d)

x6




18)



I	x12
8 x 50	

19)



OK